



ALLANA BUICK & BERS

Building solutions.
Engineering for life.

**Critical Review of the Life Span of TPO and
PVC**

WSRCA

June 8, 2011

**Karim P. Allana, P.E., RRC, RWC
Allana Buick & Bers, Inc.**

Karim Allana, P.E., RRC, RWC

CEO / Senior Principal

EDUCATION: B.S., Civil Engineering, Santa Clara University

REGISTRATION: P.E., Civil Engineering, Hawaii, California, and Nevada

CERTIFICATION: Registered Roof Consultant (RRC), Roof Consultants Institute (RCI);
Registered Waterproofing Consultant (RWC), Roof
Consultants Institute (RCI)

OVERVIEW:

- Former Turner Construction Employee (Project Engineering and Superintendent).
- Over 20 years experience providing superior technical standards in all aspects of building technology.
- Principal consultant in forensic investigations of building assemblies, failure analysis, evaluation and design of building infrastructure, and building envelope evaluation and design.
- Expert in all aspects of building envelope technology.
- Completed numerous new construction, addition, rehabilitation, remodel, and modernization projects for public and private sector clients.
- Specialization in siding, roofing, cement plaster, wood, water intrusion damage, window assemblies, storefronts, below grade waterproofing, and complex building envelope and mechanical assemblies.



Presentation Objectives

- ✓ Review the issues that impact the effectiveness and longevity of single ply PVC and TPO roofs.
- ✓ Present a forensic evaluation of some of the oldest PVC roofs (18 years old) and TPO roofs (11-12 years old).
- ✓ Discuss how physical forces (water, sun, rain) affect TPO and PVC.
- ✓ Discuss how design and use affect the life of TPO and PVC.



History of PVC Roofing

- Vinyl gas discovered in 1800's but no commercial use.
- Vinyl compound discovered at BF Goodrich in 1920's.
- 1930's – limited commercial uses found for PVC.
- Mid 1960's, single ply roof covers are introduced.
- Early 1970's, vinyl roofing membranes.
- Mid 1970's, oil shortage causes higher asphalt costs, single ply membranes become more cost effective.
- Early 1980's – PVC roofs are widely installed in the US.



PVC Chemistry

- **Polyvinyl chloride (PVC) is a vinyl thermoplastic polymer constructed of repeating vinyl groups (ethenyls): through chemical reaction, hydrogen atoms are replaced with a chlorine in the form of chloride.**
- **Roughly half of the PVC compound is chlorine and roughly half is vinyl and additives.**
- **Third most commonly used plastic (after polyethylene and polypropylene).**
- **Naturally stiff and light.**
- **Among the most widely used plastic in construction applications.**



PVC Chemistry (Continued)

- **Some concerned citizens called for the cessation of PVC manufacture and use – production and incineration create dioxin, a toxic chemical.**
- **Additives such as Phthalate” plasticizer needed for softening.**
- **Some plasticizers are water soluble and thus can possibly leach from PVC roofs.**
- **Phthalates have been reported by some, to create health issues.**
- **Other additives: biocides, fire retardants, pigments, and to prevent oxidation**



PVC Chemistry (Continued)

- The industry has reported to us the replacing of early phthalates with high molecular weight varieties that do not leach from roofs, such as changing from “711P” to 911P or DPHP.
- Earlier PVC roofs also used compounds containing heavy metals, as fire inhibitors.
- The industry now reports the use of Antimony Trioxide (Sb_2O_3) as a fire inhibitor.
- Some conversion to Magnesium Hydroxide as a fire inhibitor in PVC roofs.



ASTM Standard D4434 for PVC

- **Last Updated: February 2009**
- **Heat age testing (Practice D3045): 176 degrees F for 56 days**
- **Physical properties**
 - Minimum thickness (45 mil for Type I and II, 91 mil for Type III)
 - Minimum thickness over scrim (16 mil over scrim for all Types)
- **D4434 also contains these standards**
 - Tensile strength retention after heat aging: 90% of original
 - Elongation at break: 220 to 250% Type I; $\leq 15\%$ Type II, $\leq 25\%$ Type III
 - Breaking Strength: None for Type I, 200 lbf Type II; 275 lbf Type III
 - Tear resistance or Tear Strength: 45lbf Type I; 45lbf Type II; 90lbf Type III;
 - Must pass static and dynamic puncture resistance test
 - Weather testing for 5000 hours – see D4434 for more information



PVC Manufacturers, 2010

In alphabetical order:

- **Canadian General Tower (Mostly Manufactures Private Labels for Others)**
- **Cooley (Mostly Manufactures Private Label for Others)**
- **Duralast**
- **Flex Membrane**
- **Sarnafil**



PVC Raw Materials, 2010

In alphabetical order:

- **BASF (Additives)**
- **Exxon**
- **Formosa**
- **All have plants in the U.S.**



Antimony Trioxide as a Fire Retardant – PVC and TPO

- **Nearly all of the world's supply of antimony and antimony trioxide is in China.**
- **This has caused some instability in supply and pricing over the years.**
- **Antimony trioxide is possibly carcinogenic to humans.¹**

¹ *Source: World Health Organization, International Agency for Research on Cancer*



History of TPO Roofing

- **The TPO polymer was developed in Italy by Montell (now LyondellBasell).**
- **First applications as a waterproofing membrane were for below grade applications (pond liners) in Europe.**
- **TPO roofing membranes were introduced in the early 1990's in the U.S. with most major installations beginning in the early 1990's**
- **Early 1990s:**
 - A couple of products introduced in America
- **2007:**
 - At least 5 major American companies offer TPO
- **Issues have been reported with TPO stiffness and durability**



TPO Chemistry

- **Thermoplastic Poly Olefin (TPO) is a trade name that refers to polymer blends usually consisting of some fraction of polypropylene, polyethylene, and additives.**
- **Additives: Fire retardants, UV protection agents, anti-oxidants, others.**
- **TPO tends to be stiffer than PVC.**
- **TPO does not contain halogens or phthalates.**
- **Some early TPO membranes were black to mimic the look of EPDM.**
- **Failures reported, possibly from excessive heat.**



TPO Chemistry (Continued)

- **Early on, poly-brominated additives were added to TPO.**
- **The brominated compounds reacted with the UV stabilizers, decreasing effectiveness.**
- **This caused premature failures.**
- **Some manufacturers report having replaced these additives.**



TPO Chemistry (Continued)

- Currently, most domestic TPO manufacturers use magnesium hydroxide flame retardant systems, according to the industry.
- Much higher levels of magnesium hydroxide are required compared to antimony systems.
- As a suspension in water, magnesium hydroxide is often called *milk of magnesia* because of its milk-like appearance.
- Magnesium hydroxide is produced domestically and the supply is stable.
- This has been driven, at least partially, by dwindling availability of Antimony.



TPO Standard - ASTM D6878 – 08e*

Heat Aging Testing (test method D573):

240°F for 670 hours (28 days)

Physical Properties (test method D751):

- Minimum thickness of 39 mils
- Minimum thickness over the scrim of 12 mils

ASTM D6878 – 08e also establishes these standards under test method D751:

- Breaking Strength, minimum - 220 lbf
- Elongation at Reinforcement Break, minimum 15%
- Tearing Strength, minimum - 55lbf

ASTM D6878 – 08e establishes these standards under test method D2137:

- Brittleness Point, maximum -40 degrees C and -40 degrees F

ASTM D6878 – 08e establishes these standards under test method D471:

- Water Absorption, maximum mass $\pm 3.0\%$ (top coating only)

*

This ASTM specification is under the jurisdiction of ASTM Committee D08 on Roofing and Waterproofing and is the direct responsibility of Subcommittee D08.18 on Nonbituminous Organic Roof Coverings. ASTM D6878 – 08e was last revised on July 1 2008. No changes since that date (as of 5-24-2011) .



TPO Heat Aging Standard Under D6878 – 08e

- **Test Method D573**
- **New ASTM heat aging standard was proposed due to perceived problems with degradation caused by heat.**
- **Current Standard: Heat age for 670 hours (27.92 days) at 240 degrees Fahrenheit (116 degrees C)**
- **Proposed new higher standard sought to address some of the reported problems with TPO.**
- **New standard was voted down, in ASTM Committee.**



TPO Manufacturers, 2010

In alphabetical order:

- Carlisle
- Cooley
- Firestone
- GAF
- Johns Manville (Private label until recently)




TPO Raw Material Suppliers

In alphabetical order:

- **Chevron Phillips**
- **Chroma Corporation**
- **LyondellBasell**
- **MRC Polymers Inc.**
- **All have plants in the U.S.**



Single Ply Sales Growth 2003 - 2008




Source: Single Ply Industry



The U.S. Commercial Membrane Roofing Market

2009-2010 Estimate



Source: Consensus of Midwest Roofing Contractors Association Panel, 2010



Roofs Can, and Do, Last 30+ years

Traits of 30+ year roofs:

- **Good UV protection. Gravel surfacing, renewable acrylic coating, etc.**
- **Good Design. Details such as drains, sleepers, base flashings, all designed to last 30+ years, not just the membrane.**
- **Proper slope to drain.**
- **Proper securement of roof and insulation**
- **Stable substrate such as concrete, Lt Wt Insulating Concrete, or insulation over plywood or metal.**
- **Protection from physical damage, excessive traffic, hail, etc.**



Problem Areas to Be Discussed

- **Failings of the membrane above the scrim**
- **The scrim itself**
- **Impact of ponding water**
- **Repair issues**
- **Manufacturing issues**
- **Impact of other roof components**
- **Protection from physical damage, reflected sunlight, excessive traffic, hail, etc.**



WSRCA TPO Issues

- **WSRCA began a test in 2000: TPO Weathering Farm Project, a study of the same four manufacturers' products on four test buildings**
- **Participating companies that provided test membranes were:**
 - Carlisle
 - Firestone
 - Dow (formerly Stevens)
 - GenFlex (withdrew in 2007)
- **Test Roof Locations:**
 - Anchorage, Alaska
 - Seattle, Washington
 - Las Vegas, Nevada
 - San Antonio, Texas
- **Summary of Initial Report in 2007**
 - No significant issues found



Updated Findings in May/June 2010

- **Summary of WSRCA Findings in the Update:**
 - Seam integrity after seven years considered “normal”
 - “Some tightening of the sheets”
 - Some roof pads “have degraded significantly”
 - Hard creases created during installation had cracked in the “top coating”
 - Chalking test showed “minimal chalking or pickup”
 - “Sealant applied at cut edges of some patches and flashings appears to be reaching the end of its useful service life and in a few locations it has separated and failed”
 - Difference in color between sheets continues as does dirt accumulation, heavier on some sheets
 - “All roofs are presently leak-free and these 60-mil white TPO membranes are so far showing good in-service performance.”





ALLANA BUICK & BERS

Building solutions.
Engineering for life.

Case Study: PVC

Bay Area, California

PVC Case Study: *Department Store*

- **Large department store in Northern California.**
- **Eighteen year old roof.**
- **No repairs, no leaks, no problem?**
- **Purpose of the investigation: Determine longevity of single ply after a long period of use.**
- **We were with a team of other skeptical consultants.**



Forensic Methodology

- **Visual inspection to observe performance of system for sustainability.**
- **Limited destructive testing.**
- **Laboratory testing of samples to compare between original membrane and aged membrane.**



Sustainability Checklist

- **Roof system's ability to handle foot traffic and impact damage.**
- **Membrane's ability to handle ponding water and condensate.**
- **Membrane's ability to be patched and repaired.**
- **Membrane's physical properties, tensile strength, thickness, bend test, etc.**



Sustainability Checklist (continued)

- Was roof system sustainable for type of use (retail store)?
- Was original design of the roof system adequate for its intended use?
- Was original application (construction) installed per manufacturer's requirements?
- Could repairs be made to an 18 year old PVC membrane?



18 year old single ply roof on a department store in Northern California.

Test Cut Analysis




Test cut exposing rosin paper and insulation.





Evidence of limited amount of condensation.

Mechanical bar fastener in excellent condition.





Membrane patching (Back of sheet) was no problem.

Visual Analysis



Construction debris was observed on roof.



Design Issue



Equipment supports not integrated and secured into roof. Design of pipe supports not sustainable.





***Impact damage from
unknown source.***

Evidence of nail from
construction debris.



**Sustainability, impact
damage.**

***Membrane damage from
unknown source.***



Visual signs of chalking and age were observed in areas of ponding water.

**Cooling tower and
condensate water leaking
over roof.**



**Sustainability, ponding
water and chemicals.**

**Erosion of membrane due
to water had deteriorated
membrane, scrim is
visible.**

PVC Sustainability Score

MEMBRANE MATERIAL

- Field areas of membrane performance good 20+ years for 40 mil membrane
- Easy to patch on back of sheet. Did not attempt to patch on front of sheet

TRAFFIC AND IMPACT DAMAGE

- Susceptible from impact damage
- Damage easy to identify and repair



Sustainability Score

DESIGN

- Original poor design of pipe supports caused damage
- Poor design of roof drainage caused ponding water and damage. Membrane susceptible to ponding water
- Poor design of condensation control mechanism caused damage





ALLANA BUICK & BERS

Building solutions.
Engineering for life.

Case Study: TPO

Las Vegas, Nevada

Reviewed Over 25 TPO Roofs in Vegas

- Reviewed several manufacturers in study:
 - Carlisle
 - GAF
 - Firestone
 - Johns Manville (by private label manufacturer)
 - JP Stevens (Dow)



7 Year Old TPO: *Large Warehouse*

- **Large beer distribution warehouse in Las Vegas.**
- **Carlisle/Stevens**
- **Seven year old roof.**
- **Color difference in adjacent sheets**
- **Heat/UV damage adjacent to wall/base flashing areas**



Large Warehouse in Las Vegas, Nevada



Color Difference in Sheets



7 Years Old, Large Warehouse in Las Vegas




Typ. Equipment Well Area



7 Years Old, Large Warehouse in Las Vegas



Large Warehouse in Las Vegas, Nevada



Large Warehouse in Las Vegas, Nevada



The impact of ponding water.



Large Warehouse in Las Vegas, Nevada



Near edge of gutter, evidence of past ponding water and scrim is showing.



5 Years Old Carlisle, Hospital Building, Vegas



5 Years Old Carlisle, Hospital Building, Vegas



5 Years Old Carlisle, Hospital Building, Vegas



*Corner of parapet wall,
membrane completely gone,
Severe Damage.*




5 Years Old Carlisle, Hospital Building, Vegas



Membrane lost and glass has deteriorated.



5 Years Old Carlisle, Hospital Building, Vegas




5 Years Old Carlisle, Hospital Building, Vegas



*Next to parapet wall,
membrane severe damage.*



5 Years Old Carlisle, Hospital Building, Vegas




Owner attempted repair with visqueen and sealant

Next to HVAC unit, base flashing severe damage



5 Years Old Carlisle, Hospital Building, Vegas



5 Years Old Carlisle, Hospital Building, Vegas



Next to HVAC Unit, severe deterioration of membrane




5 Years Old Carlisle, Hospital Building, Vegas



Scrim showing, walk pad shrinking.




5 Years Old Carlisle, Hospital Building, Vegas



Significant chalking and deterioration of membrane material.




5 Years Old Carlisle, Hospital Building, Vegas




Scrim showing and frayed, heat from walk pad and reflection from HVAC unit.



Less damage on 7 Years Old Carlisle



7 Years Old Carlisle, Hospital Building, Vegas



7 Years Old Carlisle, Hospital Building, Vegas



Severe delaminating under walk pad and upper membrane layer.



7 Years Old Carlisle, Hospital Building, Vegas



Severe delaminating of under walk pad and upper membrane layer.



7 Years Old Carlisle, Hospital Building, Vegas



Moderate damage due to reflection adjacent to equipment screen posts



7 Years Old Carlisle, Hospital Building, Vegas



7 Years Old Carlisle, Hospital Building, Vegas



Moderate damage due to reflection adjacent to equipment screen posts



5 Years Old, Firestone 40 Mil, Molasky Bldg.



5 Years Old, Firestone 40 Mil, Molasky Bldg.



South side exposure, reflection and walk pad, no significant damage



7 Years Old Firestone, Agasi College, Vegas



7 Years Old Firestone, Agasi College, Vegas



*Southern Exposure however,
no reflecting wall surfaces.
Observed no accelerated
deterioration.*



7 Years Old Firestone, Agasi College, Vegas



2 years old roof (replaced due to Solar addition)

9- 10 years old roof

2 years old, New roof section has much higher dirt pickup than 9-10 year old roof



5 Years Old Firestone, Bass Sporting Goods



5 Years Old Firestone, Bass Sporting Goods



5 Years Old Firestone, Bass Sporting Goods



Corner exposure, no visible damage to membrane.



5 Years Old Firestone, Bass Sporting Goods



UNLV TPO Failures

- **UNLV owns or manages over 120 buildings in Las Vegas**
- **UNLV replaced 11 TPO roofs over the past 3 years due to premature failure**
- **Premature failures included various TPO manufacturers and involved various modes of failures. Manufacturers included:**
 - JP Stevens (Dow) – Cracks at seams
 - Johns Manville (Private label) – Cracks at seams
 - JP Stevens (Possibly Private Label) – Cracks at seams
 - Carlisle – UV – Heat failure
 - GAF – UV – Heat failure
- **Only Firestone (10 year old) roof had no failures. All other TPO roofs at UNLV have been replaced.**



UNLV, LBC Building, GAF 7 years old



*Both seam and UV/Heat failure.
(Seam failure repairs)*



UNLV, LBC Building, GAF 7 years old



UV/Heat failure. There are no reflective areas. Failures in the field of the roof




UNLV LLB Building, Dow/Stevens



Seam Failure



UNLV LLB Building, Dow/Stevens



Typical seam crack/split failure.



UNLV, BSL Bridge Way, Carlisle, 10 years old



UV/Heat failure. Clear story window reflection



UNLV, BSL Bridge Way, Carlisle, 10 years old



UV/Heat failure. Window reflection



UNLV, ARC Building, GAF TPO 2.5 years old




Original GAF roof failed in 3 years. GAF replaced it march 2008. New Roof also failing



UNLV, ARC Building, GAF TPO 2.5 years old



This replacement GAF roof is less than 3 years old!



UNLV Bookstore, Firestone 11 Years Old

Roof has south facing stucco parapet. No heat related failures were observed



UNLV Bookstore, Firestone 11 Years Old



Roof has south facing stucco parapet. No heat related failures were observed



UNLV Bookstore, Firestone 11 Years Old



While there were no heat related failures, all attempts to heat weld/patch the roof were unsuccessful.



Las Vegas TPO Round 2

- **Six Carlisle Roofs, 10 - 15 Years Old.**
- **Planet Hollywood (Formerly the Aladdin)**
- **Town and Country Ford**
- **Sunset Station Casino**
- **Las Vegas Valley Water District**
- **Country Club Towers**
- **Southwest Medical Associates**
- **Similar issues:**
 - **Failures due to heat and reflected light**
 - **Walk Pads**
 - **Surface Deterioration and Chalking**



Aladdin Hotel – Planet Hollywood



Carlisle Roofs – 12 years Old



Walk pad damage



Walk pads had been removed and damaged areas repaired



Typical damage at walk pads



Seam and walk pad issues



Town & Country Ford Dealership



Carlisle Roof

Extensive Damage to Membrane Surrounding A/C Units




UV Damage at North Parapet



UV Damage at walk pad at the bottom of the transition ladder



UV Damage at Edge of Walk Pad




Chalking



Sunset Station Casino – Cinema Area

Oldest Roof in Group – 14 years old, in the best shape of all.



North Parapet Wall



North parapet wall shows minimal signs of change in the roof membrane.



Grease Fan



Minimal damage, possibly due to type of vegetable oil used.



TPO Sample Thickness Test

UNLV Bookstore-Seam Sample (Exposed)

	Overall Thickness (m-in)	Thickness Over Scrim (m-in)
Sample #1	40.30	19.17
Sample #2	41.40	19.91
Sample #3	40.06	20.04
Average	40.59	19.71

UNLV Bookstore-Seam Sample (Unexposed)


Sample #1	42.98	23.07
Sample #2	42.63	22.11
Sample #3	43.73	23.46
Average	43.11	22.88

UNLV Bookstore-Near South Facing Wall

Sample #1	41.07	19.95
Sample #2	40.80	20.54
Sample #3	42.73	20.89
Average	41.53	20.46



TPO Material Thickness



Sysco, Las Vegas, Firestone 8 Years Old



*Roof age ranges from 2002,
2004 and 2008 expansion*



Sysco, Las Vegas, Firestone 8 Years Old



South side, next to HVAC and black walk pads, no heat related failures observed



Sysco, Las Vegas, Firestone 8 Years Old



*Fully adhered section failed in
adhesion. Roof was
mechanically fastened and
seam tape repaired*



Sysco, Las Vegas, Firestone 8 Years Old



*White metal paneled clearstory
had some UV/heat damage*



Sysco, Las Vegas, Firestone 8 Years Old



White metal paneled clearstory had some UV/heat damage



TPO Sustainability Score

UV – Heat Damage

- All membrane manufacturers suffered some level of damage
- GAF fared the worst. Firestone fared the best
- Failures appear to be mostly adjacent to parapet walls, reflection from clear story windows and metal panels
- More failures in hot climate zones like Las Vegas
- GAF failure was documented throughout the roof in UNLV case; started adjacent to clear story window but spread throughout the roof

Seam Crack/Split Issue

- Appears to be limited to some manufacturers
- Failures were observed in JP Stevens and Johns Manville



Cause of Failure?

- **Most TPO membranes are made from same or similar base polymers, Basell**
- **Formulations vary due to different additives (or packages) which are 2% to 3% of material volume but very costly.**
- **Packages include:**
 - UV Stabilizers and absorbers
 - Light stabilizers
 - Antioxidants
 - Fire retardants
- **Different manufactures use different chemistry and ratio for additives**
- **UV stabilizers and Antioxidants may need to be improved?**



Lessons Learned

- Sustainability depends on many factors, some of which could have been due to the manufacturing process.
- Membrane's ability to handle normal exposure to sun, especially reflected light, could be an issue
- Repairs may be necessary immediately
- Weldability of older TPO continues to be an issue
- Owners will need frequent inspections, timely repairs, and use of proper patching techniques.
- PVC appears to be performing better although Author did not conduct study of TPO performance in high heat/reflected areas in Las Vegas type climate. More study is needed to compare.
- Neither PVC or TPO lose appreciable membrane thickness.

