

# Southwest Medical Associates – 12 years old





# Minor UV degrading noted at the north and east parapet



# Minor UV at the west side of the A/C unit



# Country Club Towers – 12 years old





# Heavy foot traffic but no visible damage to the roof



White walk pad had been installed at the top of the access stairs, but no visible damage to the roof membrane



# No parapet for reflection, and no visible roof membrane damage



The black roof pads are partially shaded during the day and no roof membrane damage was noted



One area had previously been coated by the reason for the coating is unknown



Roofing membrane was inverted and used under the A/C unit for protection





# Las Vegas Valley Water District -



# Decorative wing walls on the roof



# Damage to the membrane from cable wear and discharge from a generator



# Wing wall flashing have UV damage throughout the complex



# Typical damage to the flashing at the wing walls



Ponding water areas in the field were checked but no substantial change of the membrane

